

# College Station ISD

2007 Bond Project Update

July 15, 2008

# Creek View Elementary School

# Gym and Cafeteria Area



Photo taken 07/11/2008

# Masonry on Gymnasium



Photo taken 07/11/2008

# Slab in Classroom Wing



Photo taken 07/11/2008



# Grade Beams in Classroom Wing



Photo taken 07/11/2008

# Grade Beam Forms and Steel in Classroom Wing



Photo taken 07/11/2008



# Grade Beam Forms and Piers



Photo taken 07/11/2008



# Eagle Drive Looking East



Photo taken 07/11/2008

# Entrance to Creek View Elementary from Eagle Drive



Photo taken 07/11/2008

# Eagle Drive Looking West



Photo taken 07/11/2008

College Hills  
Elementary School



# Temporary Parking Facility



Photo taken 07/11/2008

# Temporary Parking Facility



Photo taken 07/11/2008

# Temporary Parking Facility



Photo taken 07/11/2008



# Drill Rig for Support Piers



Photo taken 07/11/2008



# Steel for Support Piers



Photo taken 07/11/2008

# Kitchen Rough-In Plumbing



Photo taken 07/11/2008



# Kitchen Rough-In Plumbing



Photo taken 07/11/2008

# Kitchen Rough-In Plumbing



Photo taken 07/11/2008



# Kitchen Rough-In Plumbing



Photo taken 07/11/2008

# Construction Site Looking South to North



Photo taken 07/11/2008

# Athletics Complex Renovations



# Multi-Sport Field House Exterior



Photo taken 07/11/2008

# Multi-Sport Field House Interior



Photo taken 07/11/2008

# Multi-Sport Field House Interior



Photo taken 07/11/2008



# Multi-Sport Field House Interior



Photo taken 07/11/2008

# Stadium Field House Weight Room Ceiling



Photo taken 07/11/2008

# Stadium Field House Ceiling Grid



Photo taken 07/11/2008



# Stadium Field House Electrical and Data Outlets



Photo taken 07/11/2008

# Stadium Field House Casework



Photo taken 07/11/2008

# Stadium Field House Casework



Photo taken 07/11/2008



# Stadium Field House Casework



Photo taken 07/11/2008

# Stadium Field House Painting



Photo taken 07/11/2008

# Stadium Field House Painted Ceiling



Photo taken 07/11/2008



# Stadium Field House Showers



Photo taken 07/11/2008

# Elevator to Press Box



Photo taken 07/11/2008

# Ground Floor Entrance to Press Box Elevator

(Plastic Protective Covering)



Photo taken 07/11/2008



# Upper Level Entrance to Press Box Elevator

(Plastic Protective Covering)



Photo taken 07/11/2008

# Stadium Home Side Men's Restroom



Photo taken 07/11/2008

# Stadium Home Side Ladies Restroom



Photo taken 07/11/2008



# Track Surface and Artificial Turf



Photo taken 07/11/2008

# Track Surface and Artificial Turf



Photo taken 07/11/2008

# Track Surface and Artificial Turf



Photo taken 07/11/2008



# Grounds Department

# Office And Restroom Building Addition



Photo taken 07/11/2008

# Material Storage Bins



Photo taken 07/11/2008



# Grounds Equipment Storage Building



Photo taken 07/11/2008