

# College Station ISD

2007 Bond Project Update

September 17, 2008

Creek View  
Elementary School

# Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

# Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008



# Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

# Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008



# Roof Joists and Decking Electrical Rough-In



Photo Taken 09/16/2008

# Plumbing Rough-In



Photo Taken 09/16/2008



# Plumbing Rough-In



Photo Taken 09/16/2008

# Plumbing Rough-In



Photo Taken 09/16/2008

# Plumbing Rough-In



Photo Taken 09/16/2008



# Stage Area



Photo Taken 09/16/2008

# Stage Area



Photo Taken 09/16/2008



# HVAC Rough-In



Photo Taken 09/16/2008



# HVAC Rough-In



Photo Taken 09/16/2008

# HVAC Rough-In



Photo Taken 09/16/2008



# HVAC Rough-In



Photo Taken 09/16/2008



# Gym Interior and Partial Roof Deck



Photo Taken 09/16/2008

# Exterior Walls



Photo Taken 09/16/2008

# Exterior Walls



Photo Taken 09/16/2008



# Kitchen Service Entrance



Photo Taken 09/16/2008

# Gym Exterior



Photo Taken 09/16/2008

# Masonry Work



Photo Taken 09/16/2008



# Masonry Work



Photo Taken 09/16/2008

# Masonry Work



Photo Taken 09/16/2008

College Hills  
Elementary School



# Gym Structural Masonry



Photo Taken 09/16/2008

# Gym Structural Masonry



Photo Taken 09/16/2008

# Grade Beams



Photo Taken 09/16/2008



# Grade Beams



Photo Taken 09/16/2008

# Grade Beams and Slab Transition Area



Photo Taken 09/16/2008



# Grade Beam Forms



Photo Taken 09/16/2008



# Grade Beam Forms



Photo Taken 09/16/2008

# Slab Transition Area



Photo Taken 09/16/2008