

College Station ISD

2007 Bond Update

February 20, 2009

College Hills Elementary School

Entrance Area



Photo taken 02/20/2009

Entrance Area



Photo taken 02/20/2009

Entrance Area



Photo taken 02/20/2009

Covered Canopy



Photo taken 02/20/2009

Stage in Cafetorium



Photo taken 02/20/2009

Kitchen Area



Photo taken 02/20/2009

Walk-in Freezer and Refrigerator



Photo taken 02/20/2009

Kitchen Area



Photo taken 02/20/2009

Modified Bitumen Roof System



Photo taken 02/20/2009

Modified Bitumen Roof System



Photo taken 02/20/2009

Casework Awaiting Installation



Photo taken 02/20/2009

Corridor View



Photo taken 02/20/2009

Library Area



Photo taken 02/20/2009

Library Area



Photo taken 02/20/2009

Retaining Wall



Photo taken 02/20/2009

Casework Awaiting Installation



Photo taken 02/20/2009

Exterior View



Photo taken 02/20/2009

Exterior View



Photo taken 02/20/2009

Exterior View



Photo taken 02/20/2009

Creek View Elementary School

Covered Canopy at Entrance



Photo taken 02/20/2009

Exterior View of Bus Drop-off Area



Photo taken 02/20/2009

Stage in Cafetorium



Photo taken 02/20/2009

Cafetorium Area



Photo taken 02/20/2009

Kitchen Area



Photo taken 02/20/2009

Kitchen Serving Area



Photo taken 02/20/2009

Kitchen Equipment



Photo taken 02/20/2009

Corridor View



Photo taken 02/20/2009

Music Room



Photo taken 02/20/2009

Music Room



Photo taken 02/20/2009

Music Room



Photo taken 02/20/2009

Reception Desk Area



Photo taken 02/20/2009

Office Area



Photo taken 02/20/2009

Corridor View



Photo taken 02/20/2009

Library Entrance



Photo taken 02/20/2009

Hand Wash Area



Photo taken 02/20/2009